Atlantic Home Inspection Company LLC



Confidential Home Inspection Report

0 Main Street Uptown

Maine

00000

1000

1/1/2000





By Keith Lefebvre Atlantic Home Inspection Company LLC Lyman, Maine

www.atlantichi.com

Phone: 207-283-HOME

A Proud Member of the Best Inspectors Network™

Atlantic Home Inspection Company

Table of Content

1000

- 1 General
- 2 **Utilities**
- 3 Grounds
- 4 Roof
- 5 Chimney
- 6 Structure, Exterior
- 7 Garage
- 8 Kitchen
- 9 Rooms
- 10 Bathrooms 1-2
- 11 Bedrooms 1-2
- 12 Attic
- 13 Foundation
- 14 Electrical A
- 15 Plumbing
- 16 Water Heater
- 17 Heating
- 18 Summary
- 19 <u>Titanium</u>

Atlantic Home Inspection Company LLC

General Information

1000

Building Description

Age (approximate)	Description / Type	Address / Comments
rigo (approximato)	1000	0 Main Street
Area (approximate)	1000	Uptown, Maine, 00000
		Date of Inspection: 1/1/2000
Building type	Single family	
	Single family, split level	
	Single family, ranch	
	See comments	-
Construction	Not applicable	
	X Frame	
	Brick	
	See comments	
Additional Buil	ding Description/ Comme	ents
Additional Dun	ang Description/ Comme	
	ghout this report indicating damage fety hazard if not repaired.	or items marked as needing repair may result in further damage or may
present a neath or sai		
	iet, nazara ii net repairea.	
Client Informat		
Client Informat	tion	
Name		Doe
Name Address	tion	
Name Address Phone(s)	tion	Doe E-mail
Name Address	tion	
Name Address Phone(s)	tion	
Name Address Phone(s) Buyer's agent	tion	E-mail
Name Address Phone(s) Buyer's agent Phone(s)	tion	E-mail
Name Address Phone(s) Buyer's agent Phone(s) Seller's agent	tion	E-mail E-mail
Name Address Phone(s) Buyer's agent Phone(s) Seller's agent Phone(s)	tion	E-mail E-mail
Name Address Phone(s) Buyer's agent Phone(s) Seller's agent Phone(s) Lockbox/Other	John	E-mail E-mail
Name Address Phone(s) Buyer's agent Phone(s) Seller's agent Phone(s) Lockbox/Other	John Instructions	E-mail E-mail

qualified professional. It is our mission to identify all safety hazards and major defects. All major defects are also considered safety hazards. All building and safety code compliance and issues should be addressed with your local code enforcement officer. The inspection "Standards" used for this inspection are Inter "NACHI" standards.

Weather at time of inspection


Temperature	Start Time	General Conditions
50's	9:00 a.m.	Sunny

Utilities 1000

	I = Inspected			ed	NI = Not Inspected NP = Not Present R =	Repair Needed D = Defective
<u></u>	⊗ NI	⊗ NP	R	⊗ D	Item Comments	Item
X	ш	Ш	Ш	Ш	Electric	Public utility
X	ш	Ш	Ш	Ш	Oil	Public utility
Ш	Ш	X	Ш	Ш	Back-up gas	Public utility
	ш	X	Ш	Ш	Propane	Public utility:
X	Ш	Ш	Ш	Ш	Water	Public utility
						4
Ш	ш	X	Ш	Ш	Deep well	Private:
			_			, , , , , , , , , , , , , , , , , , ,
Ш	ш	×	Ш	Ш	Point well	Private
Ш	Ш	X	Ш	Ш	Generator	Private
X	ш	Ш	Ш	Ш	Sewage	Public Utility
Ш	Ш	X	Ш	Ш	Septic	Private



Grounds 1000






Roof 1000

Covering and Structure

	I	= Ins	pect	ted	NI = Not Inspected NP = Not Present	R = Repair Needed D = Defective
<u></u>	<mark>⊗</mark> Ni	O NP	R	⊗ D	Item Comments	Condition
X					Shingles	Good
					The home has architectural shingles.	
X	ш	Ш	Ш	Ш	Ridge vent	Good
X	Ш	Ш	Ш	Ш	Roof deck	Good
<u> </u>			_			
X	ш	Ш	Ш	Ш	Flashing	Good
X	Ш	Ш	×	X	Ventilation	Repair
					See attic space for more information.	
X	Ш	Ш	Ш	Ш	Drip and rake edges	Good
×	ш	Ш	Ш	Ш	Gutters, downspouts	Good
X	Ш	Ш	Ш	Ш	Age	Good
					Architectural shingles have an approximate li old).	ife span of 30 years. Roof installed in 2008 (7 years



1000

	- 1	= Ins	pect	ed	NI = Not Inspected NP = Not Present R =	Repair Needed D = Defective
<u></u>	⊗ NI	⊗ NP	R	⊗ D	Item Comments	Condition
X					Chimney structure	Good
X	ш		Ш	Ш	Сар	Good
Ш	ш	X	ш	Ш	Screen	
X	П		П	П	Flue/ liner	Good
×					Flashing	Good
	$\overline{}$	$\overline{}$	$\overline{}$			
X	ш	Ш	ш	ш	Mortar/ siding	Good
					×	
Ш	ш	X	Ш	Ш	Cricket	
X	ш	Ш	ш	ш	Cleanout	Good



Structure 1000

and Exterior

	I = Inspected		ted	NI = Not Inspected NP = Not Present R =	Repair Needed D = Defective
♂	NI N	P R	⊗ D	Item Comments	Condition
X				Siding	Good
				The home has vinyl siding.	
X			X	Fascia, soffits, trim	Good
				The home has aluminum wrapped trim. There is some decay. The door jamb of the front door has	
×				Doors	Good
X				Windows	Good
X	$\square \sqcup \sqcup$	Ј Ш	Ш	Screened Porch	Re-evaluate
				Due to the skirting around the screened porch, it co to the home and garage. Recommend to re-evaluate	
	<u> </u>		ш	Stairs, Bulkhead	
X				Water faucets	Good
		- — - —			
X				Window wells, crawl space vents	Good



Garage 1000

I = Inspected	NI = Not Inspected NP = Not Present R =	Repair Needed D = Defective
S S S S S S S S S S S S S S S S S S S	Item Comments	Condition
	Siding	Good
lacksquare	Fascia, soffits, trim	Good
X 🗆 🗆 🗆	Service Door, Window	Good
XUUUU	Fire Separation from living space	Good
	Overhead door(s)	Safety hazard
	The automatic garage door does not have safet	y sensors. Recommend to install sensors.
X	Electric	Safety hazard
	There is no GFCI outlet in the garage. Install a	GFCI outlet.
	Water faucets	
	Window wells, crawl space vents	
	L	






Kitchen 1000

	I = Inspected			ed	NI = Not Inspected NP = Not Present R =	Repair Needed D = Defective
<u></u>	⊗ NI	⊗ NP	R	⊗ D	Item Comments	Item
X	П	П	П	П	Kitchen/dining room	Cabinets
_	_	_		_		
X	Ш	Ш	Ш	Ш	Kitchen/dining room	Counter tops and sink
X	Ш	Ш	Ш	Ш	Kitchen/dining room	Plumbing
X	Ш	Ш	X	X	Kitchen/dining room	Electrical and lighting
					There are no GFCI outlets in the kitchen. There	•
					ground. Recommend to have a professional ma	
X	Ш	Ш	Ш	Ш	Kitchen/dining room	Windows and doors
X	Ш	Ш	Ш	Ш	Kitchen/dining room	Walls and ceiling
						_
×	Ш	Ш	Ш	Ш	Kitchen/dining room	Floor
X	Ш	Ш	Ш	Ш	Kitchen/dining room	Stove
Ш	Ш	×	Ш	Ш	Kitchen/dining room	Garbage Disposal
X	Ш	Ш	Ш	Ш	Kitchen/dining room	Refrigerator



Rooms





Bathrooms 1000

	l = In	spected	NI = Not Inspected NP = Not Present R =	Repair Needed D = Defective
<u></u>	S S NI NP	፠ ❷ R D	Item Comments	Item
X			Bathroom 1	Toilet
×			Bathroom 1	Shower and bathtub
X			Bathroom 1	Plumbing
		. — —		
X	ᄔ		Bathroom 1	Electrical and lighting
X	ШЦ		Bathroom 1	Windows, walls, doors, floor, ceiling
			All bathrooms should have a window or a vent.	
			Bathroom 2	Toilet
			Bathroom 2	Shower and bathtub
	X		Bathroom 2	Plumbing
			Bathroom 2	Electrical and lighting
			Bathroom 2	Windows, walls, doors, floor, ceiling



Bedroom 1000

	I	= Ins	pect	ted	NI = Not Inspected	NP = Not Present R = Repair Needed D = Defective
<u></u>	⊗ Ni	⊗ NP	₩ R	ॐ D	Item Comments	Item
X					Bedroom 1	Doors and windows
×	Ш	ш	Ш	Ш	Bedroom 1	Floor
X	Ш	Ш	Ш	Ш	Bedroom 1	Walls and ceiling
X					Bedroom 1	Closet
X	Ш	Ш	Ш	Ш	Bedroom 1	Electrical and lighting
×	Ш	ш	Ш	Ш	Bedroom 2	Doors and windows
×	Ш	ш	Ш	Ш	Bedroom 2	Floor
X	Ш	Ш	Ш	Ш	Bedroom 2	Walls and ceiling
×	Ш	ш	Ш	Ш	Bedroom 2	Closet
X	Ш	Ш	Ш	Ш	Bedroom 2	Electrical and lighting



Attic 1000

I = Inspected	NI = Not Inspected	NP = Not Present R = R	Repair Needed	D = Defective
S S S S S S	Item Comments	(Condition	
	Access		Good	
		the bathroom closet. Recomme of the access panel to help pre		
	Insulation	_	Good	
	2 layers of batt insular	ion.		
	Moisture	_	Good	
	There is a sign of prevnew roof and flashing	ious moisture around the chimr installed.	nney in the attic spa	ce. This was prior to the
	Stains	G	Good	
X	Rafters	G	Good	
	Trusses			一个 四个经验
XXX	Ventilation		Repair	
		ffles and the insulation is stu hrough the soffit vents. Reco		
	Attic baffles			



Foundation 1000

	I	= Ins	pect	ted	NI = Not Inspected NP = Not Present R =	Repair Needed D = Defective
% —	⊗ NI	⊗ NP	R	⊗ D	Item Comments	Condition
X					Foundation walls	Good
					Poured concrete foundation walls.	
X					Support beam	Good
		_		_		
X	Ш	Ш	Ш	Ш	Floor joists	Good
×	Ш	Ш	Ш	Ш	Support posts	Good
X	Ш	Ш	X	Ш	Floor, slab	Monitor
					There is a settlement crack in the basement concreneeded.	
×	Ш	ш	Ш	ш	Moisture	Good
×	ш	Ш	Ч	Ц	Sump pit	Good
X	Ш	Ш	X	X	Stairs/rail	Safety hazard
					There is no handrail on the right side of the sta	irs to the basement. Recommend to install a
					railing.	



Electrical 1000

I = Inspected	NI = Not Inspected NP = Not Present	R = Repair Needed D = Defective
S S S S S S S S S S S S S S S S S S S	Item Comments	Condition
	Service entrance cable/conduit	Good
X X X	Main panel There are missing screws that secure the e	Safety hazard lectrical panel cover to the panel. Recommend
	to install screws.	rectrical panel cover to the panel. Recommend
\square	Main breaker/disconnect	Good
	200 amp main breaker.	
lacksquare	Made electrode - Water line	Good
X 🗆 🗆 🗆	Made electrode - Ground rod	Good
X	Branch circuits	Safety hazard
		ne that tested open ground and reverse polarity. e is an open junction box in the basement. See
	GFCI breakers	
X	Smoke Detectors	Install
		or on each level and one CO detector to every a. There is no smoke detector in the basement.



Plumbing 1000

	I	= Ins	pect	ed	NI = Not Inspected NP = Not Present R =	Repair Needed D = Defective
~	 NI	⊗ NP	R	⊗ D	Item Comments	Condition
×					Meter and Main shut-off valve(s)	Good
Ш	Ш	X	Ш	Ш	Sump pump	
X					Vents	Good
×					Drainage	Good
×					Distribution piping	Good
×					Fittings	Good
×					Valves	Good
X					Washer & Dryer connections	Good
					There are washer and dryer connections in the base washer hookups in the basement were not inspecte	



Water Heater 1000

	l = lns	pected	NI = Not Inspected NP = Not Present R =	Repair Needed D = Defective
<u></u>	S O NP	፠ ❷ R D	Item Comments	Condition
X			Water piping, valves, and fittings	Good
			There is a Heat-Flo indirect water heater that heats	the hot water.
X	шш	шш	Valves, and fittings	Good
X	ШШ	$\sqcup \sqcup$	Temperature/Pressure Relief Valve	Good
			Danie	Cook
X		ШШ	Drain	Good
			Enclosure and pan	
×	$\sqcup \sqcup$	$\sqcup \sqcup$	Controls	Good
X	$\sqcup \sqcup$	$\sqcup \sqcup$	Age	2014
X	$\sqcup \sqcup$	$\sqcup \sqcup$	Capacity	40 US Gallons



Heating 1000

	I	= Ins	spect	ed	NI = Not Inspected NP = Not	Present R	R = Repair Ne	eded	D = Defective
~	<mark>⊗</mark> N	⊗ NP	R	⊗ D	Item Comments		Condition	on	
X					Boiler		Good		
					There is a Biasi forced hot water be 10/2014. Recommend to have yea			last ser	vice recorded was on
X					Oil Burner		Good		Do Not Remove This Card Thihodesa's Heating Service
					Riello oil fired burner.				(207) 324-0151
X					Oil piping, fittings		Good		A Company of the Company
				_					
×	Ш	Ш	Ш	Ш	Controls, Low water cut off switch		Good		
×					Pressure relief valve with extension	n	Good		
×					Flue		Good		
×	Ш	ш	ш	Ш	Age		2014		
×	Ш	Ш	Ш	Ш	Output Capacity		Unknown		



Atlantic Home Inspection Company LLC

Summary

General Information: Please read the entire report. All defects are not listed on the summary page.

This report is based on a visual, non-invasive inspection of the apparent condition of the readily accessible installed systems and components of the property existing at the time of the inspection. Latent and concealed defects and deficiencies are excluded from this inspection report. All defects listed for repair in this report should be repaired by a qualified professional. It is our mission to identify all safety hazards and major defects. All major defects are also considered safety hazards. All building and safety code compliance and issues should be addressed with your local code enforcement officer. The inspection "Standards" used for this inspection are Inter "NACHI" standards.

There is a potential trip hazard where the driveway meets the concrete floor of the garage. Recommend to repair as needed.

The brick stairs at the front of the home have gaps in the mortar, and a section of bricks has cracked on the right side. Recommend to repair the stairs as needed.

Recommend to cut back the overhanging trees to prevent the debris and moisture to the roof. Recommend to cut back the shrubs to prevent moisture to the home.

The home has aluminum wrapped trim. There is wood trim around the screened porch with some decay. The door jamb of the front door has some decay. Recommend to repair as needed.

The automatic garage door does not have safety sensors. Recommend to install sensors.

There is no GFCI outlet in the garage. Install a GFCI outlet.

There are no GFCI outlets in the kitchen. There are outlets in the kitchen that tested open ground. Recommend to have a professional make the repairs needed.

There is a section of brick wall in the living room where there are some small gaps in the mortar. Recommend to re-point the brick wall as needed.

There is an outlet in the living room that tested open ground and one that tested reverse polarity. Recommend to have a professional repair as needed.

The access panel is in the bathroom closet. Recommend to install a piece of foam insulation board on the back side of the access panel to help prevent air flow to the first floor.

There are no attic baffles and the insulation is stuffed into the soffits so there is no airflow from the ridge vent through the soffit vents. Recommend to install attic baffles to improve ventilation.

There is no handrail on the right side of the stairs to the basement. Recommend to install a railing.

There are missing screws that secure the electrical panel cover to the panel. Recommend to install screws

There are outlets in some rooms of the home that tested open ground and reverse polarity. There is no GFCI outlet in the kitchen. There is an open junction box in the basement. See above for more specifics. Recommend to have a professional make the needed electrical repairs.

There should be at least one smoke detector on each level and one CO detector to every home. There is no CO detector in the home. There is no smoke detector in the basement. Recommend to install a CO and a smoke detector.