

Continuous Radon Monitor

Model Number: 1028
Calibration Date: 11/05/2009
Monitor Time: 11/19/2009 11:11

Serial Number: 57077040
CF: 2.86

1028123-R99



Inspector Information

Jack LeClair
Atlantic_Home_Inspection_Co
20_Clearview_Dr
Arunde
Maine-04046
Phone Number: 207-283-4663
License Number: ME18600C

Customer Information

Smith
123 Main Street
Anytown
Maine-04046
Phone: 207-555 1234

Site & Condition

Year Built: 1974
SqFt: 2184


Structure Type: Frame
Monitor Location: Basement



Test Summary

Start Time: 11/16/2009 10:07
End Time: 11/18/2009 10:07
Measurement Interval(hr): 1.0
Elapse Time: 2 Days 0 hrs

Overall Avg: 11.8 pCi/l
EPA Avg: 12.1 pCi/l



***** 11/16/2009 *****

Time	Counts pCi/l	Flags
11:07	4.2	
12:07	6.3	
13:07	10.1	
14:07	11.2	
15:07	10.5	
16:07	17.1	
17:07	15.4	
18:07	12.6	
19:07	14.3	
20:07	12.9	
21:07	15.0	
22:07	11.2	
23:07	7.0	

***** 11/17/2009 *****

Time	Counts pCi/l	Flags
00:07	13.3	
01:07	12.9	
02:07	15.0	
03:07	9.1	
04:07	11.2	
05:07	17.8	
06:07	9.8	
07:07	12.6	
08:07	7.3	
09:07	13.6	
10:07	12.6	
11:07	16.1	
12:07	13.3	
13:07	10.8	
14:07	12.6	
15:07	15.4	
16:07	13.3	
17:07	14.3	
18:07	15.4	
19:07	12.9	
20:07	9.8	
21:07	8.7	
22:07	10.5	
23:07	8.4	

***** 11/18/2009 *****

Time	Counts pCi/l	Flags
00:07	12.6	

***** 11/18/2009 *****

Time	Counts pCi/l	Flags
01:07	9.1	
02:07	7.7	
03:07	11.5	
04:07	9.4	
05:07	15.0	
06:07	8.7	
07:07	13.3	
08:07	12.6	
09:07	10.8	
10:07	10.1	

Error Flags:

M Motion:

Inspector Signature _____

PC Software Version: 2.1.2.0

Embedded Software Version: 106